



MOUNTING INSTRUCTIONS







2-Fix to mechanism front zero to center of cabinet (IMAGE B).

- 3- Forwards take to mechanism. After fix to L part of the rail connected on floor of cabinet with screw (B-1).
- 3- Mount to mechanism on cover with chip board screw(B-2).

Check ro working mechanism.

UNDER - WORKBENCH UNIT MOUNTING PARTS			
ND	PART NAME		PCST
1	FRAME OF MECHANISM		2
2	FULL BASKET		2/2
3	HALF BASKET		0/1
4	YSB SCREWS		8/12
5	CHIP BOARD SCREWS		10
6	HOLDER OF BOTTLE		1
STOCK CODE: SMA9 IMAGE NO: RSM15			59

